








- | | | | |
|-----------|------------------------------------|-----------|--------------------------------|
| D | Montageanleitung | GB | Assembly instructions |
| FR | Notice de montage | IT | Istruzioni di montaggio |
| NL | Handlieding voor de montage | PL | Instrukcja montażu |
| CZ | Montážní návod | SK | Návod na montáž |
| HU | Szerelési útmutató | RO | Instrukțiuni de montaj |
| TR | Montaj talimatı | RU | Инструкция по монтажу |





№	Size/MaB (mm)	Qty	✓	№	Size/MaB (mm)	Qty	✓
1	1208x 322x 24	1		10	1047x 56x 24	1	
2	418x 280x 15	1		11	182x 56x 24	2	
3	418x 280x 15	1		12	1047x 56x 15	1	
4	418x 56x 18	1		13	120x 60x 60	4	
5	1047x 56x 18	1		14	1043x 355x 18	1	
6	418x 56x 18	1		60	1034x 139x 10	2	
7	1119x 68x 15	1		61	1034x 88x 10	1	
58	418x 50x 18	1		17	1128x 412x 3	1	
59	418x 50x 18	1					



1

A 030093
x28

C 230010
8x32
x20

D a)
x2

F 250013
3.5x15
x4

K 250012
3.5x15
x1

Gd 120020
x2

Ge 120019
x2

T 180074
x1

Assembly Details:

- 58:** Detail of assembly point on component 12, showing the installation of components Da, Ge, and Gd.
- 59:** Detail of assembly point on component 12, showing the installation of components Da, Ge, and Gd.
- Warning:** Diagram showing the correct (smiley face) and incorrect (frowny face) placement of screw C into the frame.

2

B 030110
x8

M 070017
30x30
x4

Assembly Details:

- Component B:** Diagram showing the correct orientation and placement of component B onto the frame.
- Component M:** Sequence of steps 1 and 2 showing how to install component M onto the frame.

