







- | | | | |
|-----------|------------------------------------|-----------|--------------------------------|
| D | Montageanleitung | GB | Assembly instructions |
| FR | Notice de montage | IT | Istruzioni di montaggio |
| NL | Handlieding voor de montage | PL | Instrukcja montażu |
| CZ | Montážní návod | SK | Návod na montáž |
| HU | Szerelési útmutató | RO | Instrukțiuni de montaj |
| TR | Montaj talimatı | RU | Инструкция по монтажу |







№	Size/MaB (mm)	Qty	✓	№	Size/MaB (mm)	Qty	✓
1	1801x420x39	1		15	350x130x14	3	
2	533x160x33	3		16	350x130x14	3	
3	504x267x18	6		17	485x130x14	3	
4	711x378x15	1		18	589x225x3	2	
5	711x378x15	1		19	494x342x3	3	
6	711x50x18	1		20	556x225x3	1	
7	711x50x18	1		21	260x32x24	2	
8	1717x71x18	1		22	293x50x15	2	
9	1653x50x15	2		23	180x50x50	4	
10	1767x403x18	1		24	570x367x15	2	
11	207x388x18	2		25	538x367x15	1	
12	510x388x18	2		26	180x50x50	1	
13	1717x71x18	1		27	528x277x3	2	
14	1717x71x18	1		28	528x294x3	4	
				29	509x17x7	3	




2



3



4






5

B 030110
x4



P 030033
7x50
x6

Q 110021
SW4
x1



6

B 030110
x6




7

B 030110
x10

P 030033
7x50
x4


Q 110021
SW4
x1




8

B 030110
x8










S 250025
3.5x40
x3












9



9



10



11

G 190011
x12

L 250012
3,5x15 x6

N 250001
2,5x16 x24

Z1 090004
8x40 x2

Z2 180080
76x31x15 x2

Z3 250012
3,5x15 x2

Z4 250044
4x40 x2

